

## 2015 MEXICAN GRAND PRIX

From The FIA Stewards of the Meeting Document 41

To The Team Manager. Date 01 November 2015

McLaren Honda
Time 10:55

The Stewards, having received a report from the Technical Delegate (document 40), and having considered the following matter, determine a breach of the regulations has been committed by the competitor named below and impose the penalty referred to.

No / Driver 22 - Jenson Button

Competitor McLaren Honda

**Time** 10:14

Session Qualifying

**Fact** A 12th, Turbo Charger and 12th MGU-H have been used.

**Offence** Breach of Article 28.4 (a) of the FIA Formula One Sporting Regulations.

**Decision** Drop of 15 grid positions, comprising:

1) 10 grid positions for 12th TC (1st 12th element used)

2) 5 grid positions for 12th MGU-H (1st remaining 12th element used)

**Reason** A 12th TC and 12th MGU-H have been used by car 22. This is a breach of Article 28.4

a) of the FIA Formula One Sporting Regulations. In accordance with Article 28.4 f) a 10 grid position penalty is imposed, as this is the first time 12th power unit element has

been used.

A 5 grid position penalty is imposed for the MGU-H as this is the first time a 12th of

any of the remaining elements have been used.

The team notified the Technical Delegate of the change of the TC and MGU-H on the

31st October, at 11:32.

Gerd Ennser Silvia Bellot

Mark Blundell Jorge Rodriguez

The FIA Stewards of the Meeting