



## 2015 BAHRAIN GRAND PRIX

---

<b>From</b>	The FIA Formula One Technical Delegate	<b>Document</b>	4
<b>To</b>	The FIA Stewards of the Meeting	<b>Date</b>	16 April 2015
		<b>Time</b>	15:13

---

Between 10:00 and 15:00 today the following cars underwent initial scrutineering:

<b>Car numbers</b>	<b>Team</b>
44, 6	: Mercedes AMG Petronas F1 Team
3, 26	: Infiniti Red Bull Racing
19, 77	: Williams Martini Racing
5, 7	: Scuderia Ferrari
14, 22	: McLaren Honda
27, 11	: Sahara Force India F1 Team
33, 55	: Scuderia Toro Rosso
8, 13	: Lotus F1 Team
28, 98	: Manor Marussia F1 Team
9, 12	: Sauber F1 Team

All the above cars were found to be in conformity with the safety requirements of the 2015 FIA Formula One Technical Regulations.

A seal was broken on the ICE number 2 of car number 14, driver Fernando Alonso, in order to replace the ICE coolant pump shaft seal for a new one.

This was done in accordance with Appendix 2, item n° 08, of the 2015 Formula One Technical Regulations.

A seal was broken on the ICE number 2 of car number 22, driver Jenson Button, in order to replace the ICE coolant pump shaft seal for a new one.

This was done in accordance with Appendix 2, item n° 08, of the 2015 Formula One Technical Regulations.

**Jo Bauer**

## **The FIA Formula One Technical Delegate**