



## 2015 AUSTRALIAN GRAND PRIX

---

<b>From</b>	The FIA Formula One Technical Delegate	<b>Document</b>	27
<b>To</b>	The FIA Stewards of the Meeting	<b>Date</b>	15 March 2015
		<b>Time</b>	13:45

---

A seal was broken on the gearbox of car number 26, driver Daniil Kvyat, in order to change the cluster shuttle valve.

This was done in accordance with Article 9.5.2 of the 2015 FIA Formula One Technical Regulations.

**Jo Bauer**

**The FIA Formula One Technical Delegate**