

## **2013 JAPANESE GRAND PRIX**

From The FIA Stewards of the Meeting Document 16

To The Team Manager Date 11 October 2013

Williams F1 Team Time 18:46

The Stewards, having received a report from the Race Director, heard from the team representatives, examined video/audio evidence and inspected the relevant parts of the car, have considered the following matter and determine a breach of the regulations has been committed by the competitor named below and impose the penalty referred to.

No / Driver 16 - Pastor Maldonado

Competitor Williams F1 Team

**Time** 11:07

**Session** Practice 1

**Fact** The rear left wheel came off the car at turn 13 during its third consecutive fast lap.

Offence Breach of Article 23.12 of the FIA Formula One Sporting Regulations and breach of

Article 14.7 of the FIA Formula One Technical Regulations.

**Decision** The competitor (Williams F1 Team) is fined €60,000.

**Reason** Examination of the parts concerned revealed that the wheel fastener had not been

completely fastened, thus not engaging the first retaining plunger. This is a breach of Article 23.12 of the FIA Formula One Sporting Regulations. The secondary retaining plunger failed to keep the wheel in place. This is a breach of Article 14.7 of the FIA

Formula One Technical Regulations.

This is regarded as a serious safety issue.

The team has assured the Stewards that the appropriate measures will be

immediately implemented to ensure compliance.

The team cooperated completely with the Stewards during the investigation.

Garry Connelly Jose Abed

Emanuele Pirro Takashi Mitarashi

The FIA Stewards of the Meeting