



2015 CANADIAN GRAND PRIX

From	The FIA Formula One Technical Delegate	Document	4
To	The FIA Stewards of the Meeting	Date	04 June 2015
		Time	15:11

Between 10:00 and 15:05 today the following cars underwent initial scrutineering:

Car numbers	Team
44, 6	: Mercedes AMG Petronas F1 Team
3, 26	: Infiniti Red Bull Racing
19, 77	: Williams Martini Racing
5, 7	: Scuderia Ferrari
14, 22	: McLaren Honda
27, 11	: Sahara Force India F1 Team
33, 55	: Scuderia Toro Rosso
8, 13	: Lotus F1 Team
28, 98	: Manor Marussia F1 Team
9, 12	: Sauber F1 Team

All the above cars were found to be in conformity with the safety requirements of the 2015 FIA Formula One Technical Regulations.

A seal was broken on the gearbox of car number 26, driver Daniil Kvyat, in order to inspect the gear ratios and associated dog rings for physical damage and as a consequence of this inspection to change the 1st/3rd gear dog ring for another of identical specification.

This was done in accordance with Article 28.6d of the 2015 Formula One Sporting Regulations.

A seal was broken on the gearbox of car number 22, driver Jenson Button, in order to inspect the gear ratios and associated dog rings for physical damage and as a consequence of this inspection to change 2nd, 4th, 7th and 8th change gear ratio pair and 5th/7th and 6th/8th gear dog rings for others of identical specification.

This was done in accordance with Article 28.6d of the 2015 Formula One Sporting Regulations.

Jo Bauer

The FIA Formula One Technical Delegate