

2018 BAHRAIN GRAND PRIX

5 - 8 April 2018

From	The Stewards	Document	27
To	The Team Manager, Red Bull Toro Rosso Honda	Date	08 April 2018
		Time	18:47

The Stewards, having received a report from the Race Director, have considered the following matter and determine the following:

No / Driver 28 - Brendon Hartley

Competitor Red Bull Toro Rosso Honda

Time 18:14

Session Race

Fact Car 28 collided with car 11 in turn 4.

Offence Involved in an incident as defined by Article 38.1 of the FIA Formula One Sporting Regulations.

Decision 10 Second Time Penalty
(2 penalty points awarded, 2 points in total for the 12 month period)

Reason The Stewards examined video evidence and the driver of car 28 braked late for turn 4 causing the collision with car 11.
The Stewards determined that the driver of car 28 was wholly to blame for the collision.

Gerd Ennser

Paolo Longoni

Danny Sullivan

Mazen Al Hilli

The Stewards