



2015 ITALIAN GRAND PRIX

From	The FIA Stewards of the Meeting	Document	13
To	The Team Manager, Scuderia Toro Rosso	Date	04 September 2015
		Time	12:31

The Stewards, having received a report from the Technical Delegate (document 7), and having considered the following matter, determine a breach of the regulations has been committed by the competitor named below and impose the penalty referred to.

No / Driver 55 - Carlos Sainz

Competitor Scuderia Toro Rosso

Time 10:07

Session Practice 1

Fact A 5th Internal Combustion Engine has been used.

Offence Breach of Article 28.4 (a) of the FIA Formula One Sporting Regulations.

Decision Drop of 10 grid positions.

Reason A 5h ICE has been used by car 55 This is a breach of Article 28.4 a) of the FIA Formula One Sporting Regulations. In accordance with Article 28.4 c) a 10 grid position penalty is imposed, as this is the first time a 5th power unit element has been used.

The team notified the Technical Delegate of the change of the ICE on the Wednesday 26th August, at 10:48.

Lars Osterlind

Tim Mayer

Danny Sullivan

Paolo Longoni

The FIA Stewards of the Meeting