

2015 CANADIAN GRAND PRIX

11

From The FIA Stewards of the Meeting Document

To The Team Manager. Date 05 June 2015

Scuderia Toro Rosso
Time 13:05

The Stewards, having received a report from the Race Director, heard from the driver and team representative, and examined video evidence, have considered the following matter and determine the following

No / Driver 55 - Carlos Sainz

Competitor Scuderia Toro Rosso

Time 11:29

Session Practice 1

Fact Car 55 was not driven immediately back onto the track from the pit stop position.

Offence Alleged Breach of 10.1 b) of the Race Director's Event Notes

Decision No further action.

Reason Prior to the pit stop the car suffered an electrical problem exiting the pit lane. The

problem appeared to be resolved and the car returned to the track, did a scheduled stop and "rubber lay" then on leaving the pit location the RPM dropped and declutching

occurred. The driver decided in the interest of safety not to return to the track.

Garry Connelly Silvia Bellot

Alan Jones Mike Kaerne

The FIA Stewards of the Meeting