



## 2015 BRAZILIAN GRAND PRIX

---

<b>From</b>	The FIA Stewards of the Meeting	<b>Document</b>	37
<b>To</b>	The Team Manager, Infiniti Red Bull Racing	<b>Date</b>	15 November 2015
		<b>Time</b>	11:25

---

The Stewards, having received a report from the Technical Delegate (document 35), and having considered the following matter, determine a breach of the regulations has been committed by the competitor named below and impose the penalty referred to.

**No / Driver** 3 - Daniel Ricciardo

**Competitor** Infiniti Red Bull Racing

**Time** 11:00

**Session** Qualifying

**Fact** A 5th Energy Store and 5th Control Electronics have been used.

**Offence** Breach of Article 28.4 (a) of the FIA Formula One Sporting Regulations.

**Decision** Drop of 10 grid positions, comprising :

- 1) 5 grid positions for 5th ES (1st remaining 5th element used)
- 2) 5 grid positions for 5th CE (1st remaining 5th element used)

**Reason** A 5th ES and 5th CE have been used by car 3. This is a breach of Article 28.4 a) of the FIA Formula One Sporting Regulations. In accordance with Article 28.4 f) two 5 grid position penalties are imposed for the ES and CE, as this is the first time a 5th of any of the remaining elements have been used.

The team notified the Technical Delegate of the change of the ES and CE on the 15th November, at 9:28.

**Paul Gutjahr**

**Silvia Bellot**

**Mika Salo**

**Felipe Giaffone**

**The FIA Stewards of the Meeting**