



2015 SINGAPORE GRAND PRIX

From	The FIA Formula One Technical Delegate	Document	33
To	The FIA Stewards of the Meeting	Date	20 September 2015
		Time	17:47

Technical Delegate's Report

A seal was broken on the gearbox of car number 19, driver Felipe Massa, in order to change the gearbox front cover O-ring.

This was done in accordance with Article 9.5.2 of the 2015 FIA Formula One Technical Regulations.

A seal was broken on the gearbox of car number 07, driver Kimi Räikkönen, in order to inspect the 5th and 7th change gear ratio pair and associated dog ring for physical damage and as a consequence of this inspection to change 7th change gear ratio pair and associated dog ring for others of identical specification.

This was done in accordance with Article 28.6d of the 2015 Formula One Sporting Regulations.

A seal was broken on the gearbox of car number 08, driver Romain Grosjean, in order to inspect the gear ratios and associated dog rings for physical damage.

This was done in accordance with Article 28.6d of the 2015 Formula One Sporting Regulations.

Jo Bauer

The FIA Formula One Technical Delegate