

2021 TURKISH GRAND PRIX

7 - 10 October 2021

From	The Stewards	Document	10
To	The Team Manager, Scuderia Ferrari	Date	08 October 2021
		Time	12:00

The Stewards, having received a report from the Technical Delegate (document 7), have considered the following matter and determine the following:

No / Driver 55 - Carlos Sainz

Competitor Scuderia Ferrari

Time 11:32

Session Practice 1

Fact The following Power Unit Elements have been used :

4th Internal Combustion Unit (ICE)
4th Turbo Charger (TC)
4th Motor Generator Unit – Heat (MGU-H)
3rd Energy Store (ES)
3rd Control Electronics (CE)

Offence Breach of Article 23.2 a) of the FIA Formula One Sporting Regulations.

Decision Required to start the race from the rear of the starting grid.

Reason The penalty is imposed in accordance with 23.2 b).

Competitors are reminded that they have the right to appeal certain decisions of the Stewards, in accordance with Article 15 of the FIA International Sporting Code and Chapter 4 of the FIA Judicial and Disciplinary Rules, within the applicable time limits.

Gerd Ennser

Felix Holter

Enrique Bernoldi

Fatih Altayli

The Stewards