

2022 CANADIAN GRAND PRIX

16 - 19 June 2022

From The FIA Formula One Technical Delegate Document 29

To The Stewards Date 17 June 2022

Time 19:12

Technical Delegate's Report

Before the first free practice session:

The exhaust system components of all cars were checked against the declaration submitted by the relevant team before the Event.

During the first free practice session:

The tyre starting pressures of all cars during P1 were checked.

The instantaneous fuel mass flow of all cars was checked.

The plenum temperature of all cars was checked.

After the first free practice session:

The fuel pressure of all cars during the first free practice session was checked.

The logged pressure within the engine cooling system during the first free practice session was checked on all cars.

The IVT code and calibration checksums were checked on all cars.

The IVT temperatures were checked on all cars.

The ES state of charge on-track limits were checked on all cars.

The lap energy release and recovery limits were checked on all cars.

The MGU-K power limits were checked on all cars.

The maximum MGU-K speed was checked on all cars.

The maximum MGU-K torque was checked on all cars.

The maximum MGU-H speed was checked on all cars.

During the second free practice session:

The tyre starting pressures of all cars during P2 were checked.

The instantaneous fuel mass flow of all cars was checked.

The fuel temperature of all cars was checked.

After the second free practice session:

Car number 06 was weighed.

The fuel pressure of all cars during the second free practice session was checked.

The logged pressure within the engine cooling system during the second free practice session was checked on all cars.

The IVT code and calibration checksums were checked on all cars.

The IVT temperatures were checked on all cars.

The MGU-K power limits were checked on all cars.

The maximum MGU-K speed was checked on all cars.

The maximum MGU-K torque was checked on all cars.

The maximum MGU-H speed was checked on all cars.

The custom software versions were checked on all cars.

The SECU software versions were checked on all cars.

Chassis FIA checksum was checked on all cars.

The torque control was checked on car numbers 14 and 23.

Torque sensor software version checks have been carried out on all cars.

Torque sensor calibration checks have been carried out on all cars.

The tyres used by all drivers during the sessions today have been checked.

All the above items were found to be in conformity with the 2022 FIA Formula One Technical Regulations.

Jo Bauer

The FIA Formula One Technical Delegate