

2020 BAHRAIN EVENT

26 to 29 November 2020

From	The Stewards	Document	10
To	The Team Manager, BWT HWA RACELAB	Date	27 November 2020
		Time	14:29

The Stewards, having received a report from the Race Director, have considered the following matter and determine the following:

No / Driver 16 - Artem Markelov

Competitor BWT HWA RACELAB

Time 12:49

Session Practice

Fact Car 16 spun at the exit of Turn 14. After the Driver abandoned the Car, it started rolling backwards over the track.

Offence Alleged breach of Article 12.1.1.h of the FIA International Sporting Code

Decision No further action.

Reason Car 16 spun at the exit of Turn 14. When it was safe to do so, the Driver abandoned the car and left the car in neutral as required by Article 22.5. The car was then stationary for about a minute and all of sudden started rolling backwards over the track towards the inner guardrail which created an unsafe situation. As the Driver could not have expected the Car to unbeach itself, we feel that the Driver is not to blame and therefore take no further action.

Mathieu Remmerie

Dennis Dean

Faisal Alshafei

The Stewards