



## 2015 UNITED STATES GRAND PRIX

---

|             |                                       |                 |                 |
|-------------|---------------------------------------|-----------------|-----------------|
| <b>From</b> | The FIA Stewards of the Meeting       | <b>Document</b> | 10              |
| <b>To</b>   | The Team Manager,<br>Scuderia Ferrari | <b>Date</b>     | 23 October 2015 |
|             |                                       | <b>Time</b>     | 12:38           |

---

The Stewards, having received a report from the Technical Delegate (document 6), and having considered the following matter, determine a breach of the regulations has been committed by the competitor named below and impose the penalty referred to.

**No / Driver** 5 - Sebastian Vettel

**Competitor** Scuderia Ferrari

**Time** 10:02

**Session** Practice 1

**Fact** A 5th Internal Combustion Engine has been used

**Offence** Breach of Article 28.4 (a) of the FIA Formula One Sporting Regulations.

**Decision** Drop of 10 grid positions (1st 5th element used).

**Reason** A 5th ICE has been used by car 5. This is a breach of Article 28.4 a) of the FIA Formula One Sporting Regulations. In accordance with Article 28.4 c) a 10 grid position penalty is imposed, as this is the first time a 5th power unit element has been used.

The team notified the Technical Delegate of the change of the ICE on the 15th October, at 10:54.

**Gerd Ennser**

**Nish Shetty**

**Tom Kristensen**

**Dennis Dean**

**The FIA Stewards of the Meeting**