



## 2017 ABU DHABI GRAND PRIX

---

<b>From</b>	The FIA Stewards of the Meeting	<b>Document</b>	11
<b>To</b>	The Team Manager, Scuderia Toro Rosso	<b>Date</b>	24 November 2017
		<b>Time</b>	13:18

---

The Stewards, having received a report from the Technical Delegate (document 10), have considered the following matter and determine the following:

**No / Driver** 28 - Brendon Hartley

**Competitor** Scuderia Toro Rosso

**Time** 13:00

**Session** Practice 1

**Fact** 9th Motor Generator Unit-Heat (MGU-H) has been used.

**Offence** Breach of Article 23.3 (a) of the FIA Formula One Sporting Regulations.

**Decision** Drop of 10 grid positions, 9th MGU-H (1st 9th element used).

**Reason** A 10 grid position penalty is imposed as detailed above in accordance with Articles 23.3 a) and 23.3 e).

The team notified the Technical Delegate regarding the change of the power unit elements on the 21st November, at 08:21.

**Tim Mayer**

**Enzo Spano**

**Emanuele Pirro**

**Mahir Al Badri**

**The FIA Stewards of the Meeting**