



2015 ABU DHABI GRAND PRIX

From	The FIA Stewards of the Meeting	Document	20
To	The Team Manager, Manor Marussia F1 Team	Date	28 November 2015
		Time	15:23

The Stewards, having received a report from the Technical Delegate (document 18), and having considered the following matter, determine a breach of the regulations has been committed by the competitor named below and impose the penalty referred to.

No / Driver 28 - Will Stevens

Competitor Manor Marussia F1 Team

Time 14:00

Session Practice 3

Fact 5th Control Electronics has been used.

Offence Breach of Article 28.4 (a) of the FIA Formula One Sporting Regulations.

Decision Drop of 5 grid positions, 5th CE (1st remaining 5th element used).

Reason A 5th CE has been used by car 28. This is a breach of Article 28.4 a) of the FIA Formula One Sporting Regulations. In accordance with Article 28.4 f) a 5 grid position penalty is imposed, as this is the first time any of the remaining elements have been used.

The team notified the Technical Delegate of the change of the CE on the 27th November, at 21:58.

Garry Connelly

Steve Stringwell

Derek Warwick

Khaled Bin Shaiban

The FIA Stewards of the Meeting