

2021 BRAZILIAN GRAND PRIX

11 - 14 November 2021

From The FIA Formula One Technical Delegate Document 43

To The Stewards Date 14 November 2021

Time 12:55

Technical Delegate's Report

The following parts and parameters have been replaced / changed during the Parc Fermé yesterday and today:

Mercedes:

Car 44: Rear wing assembly

RHS front brake duct drum

Car 77: LHS brake duct cross over duct

Red Bull Racing Honda:

Car 33: Brake master cylinders

Rear wing upper flap
Rear wing flap snubber

LHS front trackrod antirotation device

ICE aux oil return pipe

Parameter changes associated with the replacement of the brake master cylinders

Car 11: Brake master cylinders

Parameter changes associated with the replacement of the brake master cylinders

McLaren Mercedes:

Car 03: Strain gauge axle transmitter batteries

LHS driver mirror glass

Fwd floor bib stay

Car 04: Strain gauge axle transmitter batteries

Layshaft speed sensor #2

LHS rear outboard brake disc deflector LHS rear inboard brake disc deflector

Back-up ring on water wiggo connection on RHS cooler

Suspension closing panel

LHS rear outboard wheel speed sensor

Aston Martin Mercedes:

Car 18: Clutch assembly

Engine hydraulic pack assembly

RHS floor laser window

Parameter changes associated with the replacement of the clutch assembly

Parameter changes associated with the replacement of the engine hydraulic pack

Car 05: Clutch assembly

Parameter changes associated with the replacement of the clutch assembly

Alpine Renault:

Car 14: TPMS POS file

Car 31: MGU-K oil cooling pressure sensor

TPMS POS file

Parameter changes associated with the replacement of the MGU-K cooling pressure

sensor

Ferrari:

Car 55: RHS front brake duct drum

RHS front brake duct bypass

AlphaTauri Honda:

Car 22: Brake master cylinders

LHS and RHS front brake duct drum

Parameter changes associated with the replacement of the brake master cylinders

Car 10: Brake master cylinders

LHS and RHS front brake duct drum

Parameter changes associated with the replacement of the brake master cylinders

Alfa Romeo Racing Ferrari:

Car 07: Exhaust tailpipe bolt

Floor

Rear wing assembly (different specification)

Haas Ferrari:

Car 09: Front wing flap adjuster cap

LHS fwd lateral floor winglet

Car 47: ES oil pump

Hydraulic suspension canister block

Roll hoop ERS status light

Williams Mercedes:

Car 63: LHS rear caliper tomb

Gearbox oil filter

All above parts have been replaced with the approval of the FIA technical delegate following a written request from the team concerned, this being in accordance with Article 34.2 of the 2021 Formula One Sporting Regulations.

Jo Bauer

The FIA Formula One Technical Delegate