

2021 Brazilian Grand Prix

11 - 14 November 2021

Document From The Stewards 49

To Date The Team Manager, 14 November 2021

Mercedes-AMG Petronas F1 Team Time 17:23

The Stewards, having received a report from the Race Director, have considered the following matter and determine the following:

No / Driver 44 - Lewis Hamilton

Mercedes-AMG Petronas F1 Team Competitor

Time 15:36

Session Race

Fact Undid safety belts while in motion on the track.

Offence Breach of Appendix L Chapter III Article 4 of the FIA International Sporting Code.

Decision The driver is fined €5,000 with an additional €20,000 which is suspended through the

end of 2022.

Reason The Stewards heard from the team representative and reviewed video evidence.

> The driver of car 44, Lewis Hamilton, undid his seat belts on the in-lap at the end of the race. While the Stewards are sympathetic to the desire to celebrate, it is fundamentally unsafe to undo the seatbelts while the car is in motion. Slow speeds in these cars are very fast for an unrestrained occupant. Further, Formula 1 drivers set the example for junior categories. It is critical that junior category drivers learn the importance of using all the safety devices of the car at all times.

The suspension of the penalty is subject to compliance with Appendix L, Ch. III of the

ISC during the period specified.

Competitors are reminded that they have the right to appeal certain decisions of the Stewards, in accordance with Article 15 of the FIA International Sporting Code and Chapter 4 of the FIA Judicial and Disciplinary Rules, within the applicable time limits

Tim Mayer Matteo Perini

Vitantonio Liuzzi Roberto Pupo Moreno

The Stewards