

2022 JAPANESE GRAND PRIX

06 - 09 October 2022

From	The FIA Formula One Technical Delegate	Document	18
To	The Stewards	Date	07 October 2022
		Time	18:00

Technical Delegate's Report

During the first free practice session:

The tyre starting pressures of all cars during P1 were checked.

The engine high rev limit bands were checked on all cars.

The fuel flow meter calibration checksum was checked on all cars.

The instantaneous fuel mass flow of all cars was checked.

The fuel temperature of all cars was checked.

The plenum temperature of all cars was checked.

After the first free practice session:

The fuel pressure of all cars during the first free practice session was checked.

The logged pressure within the engine cooling system during the first free practice session was checked on all cars.

The IVT temperatures were checked on all cars.

The ES state of charge on-track limits were checked on all cars.

The lap energy release and recovery limits were checked on all cars.

The MGU-K power limits were checked on all cars.

The maximum MGU-K speed was checked on all cars.

The maximum MGU-K torque was checked on all cars.

The maximum MGU-H speed was checked on all cars.

The custom software versions were checked on all cars.

A fuel sample was taken from car number 20.

An engine oil sample was taken from car number 20.

During the second free practice session:

The tyre starting pressures of all cars during P2 were checked.

The engine high rev limit bands were checked on all cars.

The fuel flow meter calibration checksum was checked on all cars.

The instantaneous fuel mass flow of all cars was checked.

The fuel temperature of all cars was checked.

The plenum temperature of all cars was checked.

After the second free practice session:

The fuel pressure of all cars during the second free practice session was checked.

The logged pressure within the engine cooling system during the second free practice session was checked on all cars.

The IVT temperatures were checked on all cars.

The ES state of charge on-track limits were checked on all cars.

The lap energy release and recovery limits were checked on all cars.

The MGU-K power limits were checked on all cars.

The maximum MGU-K speed was checked on all cars.

The maximum MGU-K torque was checked on all cars.

The maximum MGU-H speed was checked on all cars.

The custom software versions were checked on all cars.

The SECU software versions were checked on all cars.

Chassis FIA checksum was checked on all cars.

The torque coordinator demands were checked on car numbers 63, 16, 55 and 14.

The torque control was checked on car numbers 63, 16, 55 and 14.

Torque sensor software version checks have been carried out on all cars.

Torque sensor calibration checks have been carried out on all cars.

The tyres used by all drivers during the sessions today have been checked.

A fuel sample was taken from car number 18.

The results of fuel analyses show that the fuels were the same as ones, which had been approved for use by the relevant competitors prior to the Event.

Further the density change of the fuel samples taken today was within the permitted limits.

An engine oil sample was taken from car number 18.

The engine oil samples have been analysed by FTIR spectroscopy and viscometry.

The results of the FTIR analyses show that the sampled oils were consistent with reference engine oil samples which had been approved for use by the relevant competitors prior to the Event.

All the above items were found to be in conformity with the 2022 FIA Formula One Technical Regulations.

Jo Bauer

The FIA Formula One Technical Delegate