

2014 HUNGARIAN GRAND PRIX

From The FIA Stewards of the Meeting Document 28

To The Team Manager, Date 27 July 2014

Mercedes AMG Petronas F1 Team
Time 12:03

The Stewards, having received a report from the Technical Delegate (document 27), have considered the following matter, determine a breach of the regulations has been committed by the competitor named below and impose the penalty referred to.

No / Driver 44 - Lewis Hamilton

Competitor Mercedes AMG Petronas F1 Team

Time 16:15

Session Qualifying

Fact The gearbox and survival cell has been changed.

Offence Breach of Article 28.6 a) and 28.2 of the FIA Formula One Sporting Regulations.

Decision Car 44 is required to start the Race from the Pit Lane.

Reason The gearbox of Car 44 has been changed before 6 consecutive events have expired

and the survival cell has been replaced resulting in the competitor having to start from

the Pit Lane.

Paul Gutjahr Jose Abed

Emanuele Pirro Lajos Herczeg

The FIA Stewards of the Meeting