

2015 BRAZILIAN GRAND PRIX

From The FIA Stewards of the Meeting Document 36

To The Team Manager. Date 15 November 2015

McLaren Honda
Time 11:20

The Stewards, having received a report from the Technical Delegate (document 35), and having considered the following matter, determine a breach of the regulations has been committed by the competitor named below and impose the penalty referred to.

No / Driver 14 - Fernando Alonso

Competitor McLaren Honda

Time 11:00

Session Qualifying

Fact A 12th Internal Combustion Engine, 11th Turbo Charger, 11th MGU-H and 8th MGU-K

have been used.

Offence Breach of Article 28.4 (a) of the FIA Formula One Sporting Regulations.

Decision Drop of 25 grid positions, comprising:

1) 10 grid positions for 12th ICE (1st 12th element used)

2) 5 grid positions for 11th TC (1st remaining 11th element used)
3) 5 grid positions for 11th MGU-H (1st remaining 11th element used)
4) 5 grid positions for 8th MGU-K (1st remaining 8th element used)

Reason A 12th ICE, 11th TC, 11th MGU-H and 8th MGU-K have been used by car 14. This is

a breach of Article 28.4 a) of the FIA Formula One Sporting Regulations. In

accordance with Article 28.4 f) a 10 grid position penalty is imposed, as this is the first

time 12th power unit element has been used.

Two 5 grid position penalties are imposed for the TC and MGU-H as this is the first

time an 11th of any of the remaining elements have been used.

A 5 grid position penalty is also imposed for the MGU-K as this is the first time an 8th

of any of the remaining elements have been used.

Paul Gutjahr Silvia Bellot

Mika Salo Felipe Giaffone

The FIA Stewards of the Meeting