



2014 SINGAPORE GRAND PRIX

From	The FIA Formula One Technical Delegate	Document	25
To	The FIA Stewards of the Meeting	Date	21 September 2014
		Time	17:04

A seal was broken on the gearbox of car number 07, driver Kimi Räikkönen, in order to inspect all gear ratios and associated dog rings for physical damage and as a consequence of this inspection to change 1st, 2nd, 4th and 5th gear ratio pair.

This was done in accordance with Article 28.6d of the 2014 Formula One Sporting Regulations.

Jo Bauer

The FIA Formula One Technical Delegate