



2014 ITALIAN GRAND PRIX

| | | | |
|-------------|--|-----------------|-------------------|
| From | The FIA Formula One Technical Delegate | Document | 21 |
| To | The FIA Stewards of the Meeting | Date | 06 September 2014 |
| | | Time | 12:47 |

After the third free practice session today a seal was broken on the gearbox of car number 06, driver Nico Rosberg, in order to change two layshaft speed sensors and gearbox front cover seals and to inspect all gear ratios and associated dog rings for physical damage.

This was done in accordance with Article 9.5.2 of the 2014 FIA Formula One Technical Regulations and with Article 28.6d of the 2014 Formula One Sporting Regulations.

Jo Bauer

The FIA Formula One Technical Delegate