



2013 ITALIAN GRAND PRIX

From The FIA Formula 1 Technical Delegate
To All Teams, All Officials

Document 39

Date
08 September 2013
Time 11:27

Technical Report

A seal was broken on the gearbox of car number 01, driver Sebastien Vettel, in order to inspect the gear ratios and associated dog rings for physical damage and to replace the 5th, 6th and 7th gear ratio pair and associated dog rings for new ones of the same specification.

This was done in accordance with Article 28.6d of the 2013 Formula One Sporting Regulations.

A seal was broken on the gearbox of car number 02, driver Mark Webber, in order to inspect the gear ratios and associated dog rings for physical damage and to replace the 5th, 6th and 7th gear ratio pair and associated dog rings for new ones of the same specification.

This was done in accordance with Article 28.6d of the 2013 Formula One Sporting Regulations.

A seal was broken on the gearbox of car number 04, driver Felipe Massa, in order to inspect the 2nd gear ratio pair and associated dog ring for physical damage.

This was done in accordance with Article 28.6d of the 2013 Formula One Sporting Regulations.

The engine of car number 4 has been replaced with the approval of the FIA technical delegate following a written request from the team concerned for a previously used one and this being in accordance with Article 34.1 of the 2013 Formula One Sporting Regulations.

According to Article 28.4e) of the 2013 Formula One Sporting Regulations, this replaced engine may not be used during any future qualifying session or race with the exception of the last Event of the Championship.

Jo Bauer

The FIA Formula 1 Technical Delegate