



## 2014 AUSTRIAN GRAND PRIX

---

<b>From</b>	The FIA Formula One Technical Delegate	<b>Document</b>	49
<b>To</b>	The FIA Stewards of the Meeting	<b>Date</b>	22 June 2014
		<b>Time</b>	11:00

---

A seal was broken on the gearbox of car number 44, driver Lewis Hamilton, in order to inspect the gear ratios and associated dog ring for physical damage and as a result of this inspection to replace 5th and 7th gear ratio pair and 5/7 gear dog ring.

This was done in accordance with Article 28.6d of the 2014 Formula One Sporting Regulations.

**Jo Bauer**

**The FIA Formula One Technical Delegate**