



2016 SINGAPORE GRAND PRIX

From	The FIA Formula One Technical Delegate	Document	7
To	The FIA Stewards of the Meeting	Date	16 September 2016
		Time	17:55

Technical Delegate's Report

A seal was broken on the gearbox of car number 19, driver Felipe Massa, in order to inspect the 5th and 7th change gear ratio pair for physical damage.

This was done in accordance with Article 23.6d of the 2016 Formula One Sporting Regulations.

All change gear ratio pairs have been checked for compliance with Articles 9.6.3 and 9.6.4 of the 2016 Formula One Technical Regulations.

Jo Bauer

The FIA Formula One Technical Delegate