

## 2018 BRITISH GRAND PRIX

5 - 8 July 2018

---

<b>From</b>	The FIA Formula One Technical Delegate	<b>Document</b>	4
<b>To</b>	The Stewards	<b>Date</b>	05 July 2018
		<b>Time</b>	14:55

---

### Technical Delegate's Report

Between 10:00 and 14:35 today the following cars underwent initial scrutineering:

<b>Car numbers</b>	<b>Team</b>
44, 77	: Mercedes AMG Petronas Motorsport
5, 7	: Scuderia Ferrari
3, 33	: Aston Martin Red Bull Racing
11, 31	: Sahara Force India F1 Team
18, 35	: Williams Martini Racing
27, 55	: Renault Sport Formula One Team
28, 10	: Red Bull Toro Rosso Honda
8, 20	: Haas F1 Team
14, 2	: McLaren F1 Team
9, 16	: Alfa Romeo Sauber F1 Team

All the above cars were found to be in conformity with the safety requirements of the 2018 FIA Formula One Technical Regulations.

A seal was broken on the gearbox of car number 14, driver Fernando Alonso, in order to inspect the change gear ratio pairs and associated dog rings for physical damage and as a result of this inspection to change the 1st, 2nd, 3rd, 4th, 5th, 6th, 7th and 8th change gear ratio pair and the 2nd/4th, 5th/7th and 6th/8th gear dog rings for new ones.

This was done in accordance with Article 9.5.2 of the 2018 FIA Formula One Technical Regulations and Article 23.5d of the 2018 Formula One Sporting Regulations.

Further all change gear ratio pairs of car number 14 were checked for compliance with Article 9.6 of the 2018 FIA Formula One Technical Regulations.

**Jo Bauer**

**The FIA Formula One Technical Delegate**