



## 2015 BRAZILIAN GRAND PRIX

---

<b>From</b>	The FIA Formula One Technical Delegate	<b>Document</b>	40
<b>To</b>	The FIA Stewards of the Meeting	<b>Date</b>	15 November 2015
		<b>Time</b>	14:24

---

### Technical Delegate's Report

On the grid the tread temperature and minimum tyre starting pressure of the right hand side rear tyre was checked on car number 19 after the "5-minutes" signal was given.

The temperature measured on the tread of the right hand side rear tyre of car number 19 was 137 °C, 27 °C above the maximum tread temperature of 110 °C allowed by the official tyre supplier. The corresponding tyre pressure at 137 °C was 20.6 psi, 0.1 psi above the minimum starting pressure.

I am referring this matter to the stewards for their consideration.

**Jo Bauer**

**The FIA Formula One Technical Delegate**