

2018 AZERBAIJAN GRAND PRIX

26 - 29 April 2018

From	The FIA Formula One Technical Delegate	Document	6
To	The Stewards	Date	26 April 2018
		Time	17:53

Technical Delegate's Report

Between 13:00 and 17:50 today the following cars underwent initial scrutineering:

Car numbers	Team
44, 77	: Mercedes AMG Petronas Motorsport
5, 7	: Scuderia Ferrari
3, 33	: Aston Martin Red Bull Racing
11, 31	: Sahara Force India F1 Team
18, 35	: Williams Martini Racing
27, 55	: Renault Sport Formula One Team
28, 10	: Red Bull Toro Rosso Honda
8, 20	: Haas F1 Team
14, 2	: McLaren F1 Team
9, 16	: Alfa Romeo Sauber F1 Team

All the above cars were found to be in conformity with the safety requirements of the 2018 FIA Formula One Technical Regulations.

A seal was broken on the gearbox of car number 10, driver Pierre Gasly, in order to change the LHS and RHS differential output shaft lipseals.

This was done in accordance with Article 9.5.2 of the 2018 FIA Formula One Technical Regulations.

Jo Bauer

The FIA Formula One Technical Delegate