

## 2018 AZERBAIJAN GRAND PRIX

26 - 29 April 2018

---

<b>From</b>	The FIA Formula One Technical Delegate	<b>Document</b>	30
<b>To</b>	The Stewards	<b>Date</b>	29 April 2018
		<b>Time</b>	15:05

---

### Technical Delegate's Report

The following parts and parameters have been replaced / changed during the Parc Fermé yesterday and today:

#### **Ferrari:**

Car 07: Chassis helicoil insert  
Rear floor stay helicoil insert

#### **Red Bull Racing TAG Heuer:**

Car 03: Engine cover heatshields  
Rear wing lower pylon fairing fixing

Car 33: Engine water temperature sensor  
Engine cover heatshields

#### **Williams Mercedes:**

Car 18: Oil tank O-ring  
Power steering rack  
Parameters associated with steering rack replacement

Car 35: LHS brake duct gator

#### **Renault:**

Car 27: Pylon cooling cover lockwire

Rain light AV mounts

**Scuderia Toro Rosso Honda:**

Car 28:      RHS front upper wishbone  
              RHS front lower wishbone  
              RHS front push rod  
              RHS front track rod  
              RHS front upright  
              Parameters associated with RHS front corner replacement

Car 10:      Oil catch tank link pipe

**Haas Ferrari:**

Car 08:      Gearbox assembly  
              MOOG block  
              BBW unit  
              Torque sensor and associated shaft  
              Hydraulic pump  
              Turning vane and bargeboard stud fixation  
              Parameters associated with gearbox and hydraulic block replacement

Car 20:      Bargeboard  
              Turning vane  
              Turning vane and bargeboard stud fixation

All above parts have been replaced with the approval of the FIA technical delegate following a written request from the team concerned, this being in accordance with Article 34.2 of the 2018 Formula One Sporting Regulations.

**Jo Bauer**

**The FIA Formula One Technical Delegate**