



## 2015 AUSTRIAN GRAND PRIX

---

|             |  |                 |              |
|-------------|--|-----------------|--------------|
| <b>From</b> | The FIA Formula One Technical Delegate | <b>Document</b> | 39           |
| <b>To</b>   | The FIA Stewards of the Meeting        | <b>Date</b>     | 21 June 2015 |
|             |  | <b>Time</b>     | 11:00        |

---

A seal was broken on the gearbox of car number 44, driver Lewis Hamilton, in order to inspect the change gear ratios and associated dog rings for physical damage and as a result of this inspection to replace the 6th change gear ratio pair and the associated dog ring.

This was done in accordance with Article 28.6d of the 2015 Formula One Sporting Regulations.

**Jo Bauer**

**The FIA Formula One Technical Delegate**