

## 2020 SAKHIR GRAND PRIX

3 - 6 December 2020

From The FIA Formula One Technical Delegate Document 34

To The Stewards Date 06 December 2020

**Time** 22:15

## **Technical Delegate's Report**

When car number 63 pitted for a tyre change at 21:16hrs, the team fitted on the front axle tyres allocated to car number 77. Car number 63 left the pit lane and returned after one lap in order to fit a correctly allocated set of tyres. As this is not in compliance with Articles 24.2 a) and 24.3 e), I am referring this matter to the stewards for their consideration.

**Nikolas Tombazis** 

The FIA Formula One Technical Delegate