

# 2021 SPANISH GRAND PRIX

6 - 9 May 2021

From The FIA Formula One Technical Delegate Document 29

To The Stewards Date 09 May 2021

**Time** 13:55

# **Technical Delegate's Report**

The following parts and parameters have been replaced / changed during the Parc Fermé yesterday and today:

#### Mercedes:

Car 44: LHS and RHS AV-mounts on engine break out box

Car 77: LHS and RHS AV-mounts on engine break out box

# Red Bull Racing Honda:

Car 11: Rear wing flap snubber

### McLaren Mercedes:

Car 04: Bib structure

Plank

#### **Aston Martin Mercedes:**

Car 18: AV-mounts on RHS engine break out box

Car 05: AV-mounts on RHS engine break out box

# **Alpine Renault:**

Car 31: Cylinder #4 spark plug

RHS ignition coil pack

# AlphaTauri Honda:

Car 10: Front wing/nose assembly

# Haas Ferrari:

Car 09: T-tray assembly including mounting studs

### Williams Mercedes:

Car 06: LHS and RHS bargeboard

LHS SIS sail LHS mirror lens

All above parts have been replaced with the approval of the FIA technical delegate following a written request from the team concerned, this being in accordance with Article 34.2 of the 2021 Formula One Sporting Regulations.

## Jo Bauer

The FIA Formula One Technical Delegate