



2017 SINGAPORE GRAND PRIX

From	The FIA Formula One Technical Delegate	Document	5
To	The FIA Stewards of the Meeting	Date	14 September 2017
		Time	17:17

Technical Delegate's Report

Between 12:00 and 17:10 today the following cars underwent initial scrutineering:

Car numbers	Team
44, 77	: Mercedes AMG Petronas Motorsport
3, 33	: Red Bull Racing
5, 7	: Scuderia Ferrari
11, 31	: Sahara Force India F1 Team
19, 18	: Williams Martini Racing
14, 2	: McLaren Honda Formula 1 Team
26, 55	: Scuderia Toro Rosso
8, 20	: Haas F1 Team
27, 30	: Renault Sport Formula One Team
9, 94	: Sauber F1 Team

All the above cars were found to be in conformity with the safety requirements of the 2017 FIA Formula One Technical Regulations.

A seal was broken on the gearbox of car number 94, driver Pascal Wehrlein, in order to inspect the 2nd change gear ratio pair and associated dog ring for physical damage and as a consequence of this inspection to replace 1st, 2nd, 5th and 8th change gear ratio pair.

This was done in accordance with Article 23.5d of the 2017 Formula One Sporting Regulations.

Jo Bauer

The FIA Formula One Technical Delegate